

**LEGISTAR NO. 2023-3018  
SUPPLEMENTAL ATTACHMENT  
MP2-0010 PRIMARY EFFLUENT PUMP STATION PUMP NOS. 1, 2, AND 3  
OVERHAUL AT PLANT NO. 2**

**Figure 1:**  
PEPS Pump No. 4 signs of deterioration.



**Figure 2:**  
PEPS Pump No. 4 Impeller showing signs of heavy corrosion and in need of replacement.

