

# P2 Tricking Filter-B Center Mast Replacement

*Presented by:*  
*Rob Thompson*  
*Assistant General*  
*Manager*

*Steering Committee*  
*July 27, 2022*



1

## Tricking Filter in Operation



2

2

## TF-B Rotating Mechanism Failure



### TF-B Rotary Mechanism Failure

- Center Mast is Matched Pair, Rotating and Stationary Assemblies
- Damage to Center Mast, Surface is Machined Precisely
- Extensive Damage to Top Bearing

3

3

## TF-B Center Mast Recommendation



### **Recommend to the Board of Directors to:**

- Approve a Sole Source Purchase Order Contract to Ovivo USA, LLC (Ovivo) for a direct replacement Center Mast assembly for the Plant No. 2 Trickling Filter B in an amount not to exceed \$507,272; and
- Approve a contingency of \$50,727 (10%).

4

4

Questions



5