

LEGISTAR NO. 2022-2459
SUPPLEMENTAL ATTACHMENT
RETURN ACTIVATED SLUDGE DISCHARGE PIPING REPLACEMENT AT
ACTIVATED SLUDGE PLANT NO. 1, PROJECT NO. FE20-03

Figure 1:

The Return Activated Sludge (RAS) pipelines are deteriorating, with the outer layer broken off in sections of pipe.



<u>Figure 2:</u>
The RAS pipelines are showing signs of heavy corrosion and are in need of rehabilitation.

