

LEGISTAR NO. 2024-3668
SUPPLEMENTAL ATTACHMENT
HVAC REPLACEMENTS AT PLANT NOS. 1 AND 2, PROJECT NO. FE23-06

Figure 1:

The Steve Anderson Lift Station (SALS) rooftop condensers are corroded and are at the end of their service life.



Figure 2:

The P1 City Water Pump Station wall mounted units are corroded and are at the end of their service life.



Figure 3:

The P2 Gas Compressor roof top unit is corroded and are at the end of their service life.



Figure 4:

The West and East RAS facility rooftop units at P2 are corroded and are at the end of their service life.



Figure 5:

The rectangular primary clarifier roof top units are corroded and are at the end of their service life.

