

**LEGISTAR NO. 2023-2812  
SUPPLEMENTAL ATTACHMENT  
REPLACEMENT OF GAS FLARE PIPING AT PLANT NO. 2**

**Figure 1:**

The digester gas handling pipes are showing signs of deterioration.



**Figure 2:**

The digester gas piping system that connects to the three digester gas flares is showing signs of heavy corrosion and is in need of replacement.

