

# Cen Gen Engine No. 1 Inspection and Repairs, Specification No. BSS-2026-728BD

Riaz Moinuddin,  
Director of Operations & Maintenance

Operations Committee  
April 1, 2026



1

## CEN GEN ENGINES

Provide heating for digesters and generate power for the treatment plant.

On January 27, 2026, Engine No. 1 had a premature failure on cylinder 3 right (3R).



2

2

**Piston  
damage  
from  
previous  
failure in  
2018**



3

3

**Cylinder  
wall  
Damage  
(2018)**



4

4

Initial inspections with a borescope on Engine No. 1 cylinder 3R show similar damage to one cylinder.

Scope of work is to repair one piston/cylinder assembly and verify extent of damage.



5

5

## Recommendation

Recommend to the Board of Directors to:

- A. Approve a Sole Source Service Contract with Cooper Machinery Services LLC for inspection and field service repairs to Central Generation (Cen Gen) Engine No. 1, Specification No. BSS-2026-728BD, for a total amount not to exceed \$142,923, plus applicable sales tax and freight; and
- B. Approve additional allowance funding not to exceed \$120,000 for associated repairs that may be required due to the high potential for additional damage identified during disassembly and inspection.

6

6