

LEGISTAR FILE NO. 2023-3130 SUPPLEMENTAL ATTACHMENT GAS COMPRESSOR CYLINDERS FOR SPARE INVENTORY

Figure 1: Gas Compressor Cylinders



Figure 2:

A Gas Compressor Cylinder showing signs of biproducts of corrosion and in need of replacement from a recent overhaul.



Page 1 of 1